

DEPARTMENT OF ADMINISTRATION

GENERAL SERVICES AGENCY

AHENSIAN SETBISION HINIRAT 148 ROUTE 1 SOUTH MARINE CORPS DRIVE, PITI, GU 96915 TELEPHONE: (671) 475-1707/1708 FAX: (671) 472-4217/1727

EMAIL: GSAPROCUREMENT@GSADOA.GUAM.GOV WEBSITE: WWW.GSA.DOA.GUAM.GOV



EDWARD M. BIRN DIRECTOR (DIREKTOT)

BERNADINE C. GINES DEPUTY DIRECTOR (SIGUNDO DIREKTOT)

February 10, 2023

Invitation For Bid GSA-013-23 CCTV Surveillance System Upgrade

AMENDMENT #2

- 1. Amend to replace page 33 of 38 with the "Revised page 33 of 38 Dated 02.10.23" (Note: Language that have been included have been highlighted in yellow for quick reference)
- 2. Amend to replace page 34 of 38 with the "Revised page 34 of 38 Dated 02.10.23" (Note: Language that have been included have been highlighted in yellow for quick reference)
- 3. Amend to replace page 37 of 38 with the "Revised page 37 of 38 Dated 02.10.23"
- Amend to replace page 38 of 38 with the "Revised page 38 of 38 Dated 02.10.23"
- 5. Amend page 3 of 38.

From:

This bid shall be submitted in duplicate and sealed to the issuing office above no later than (Time) 10:00am, Date: 02/15/2023 and shall be publicly opened. Bid submitted after the time and date specified above shall be rejected. See attached General Terms and Conditions, and Sealed Bid Solicitation for details.

To now read:

This bid shall be submitted in duplicate and sealed to the issuing office above no later than (Time) 10:00am, Date: 02/20/2023 and shall be publicly opened. Bid submitted after the time and date specified above shall be rejected. See attached General Terms and Conditions, and Sealed Bid Solicitation for details.

All others remain unchanged.

Chief Procurement Officer

Please Print Acknowledgement Copy (Re-Fax to GSA)

Received By: Date:

Company Name:
Fax to: 475-1727 or 472-4217
Equal to: esaprocurement@esa

ITEM NO.	DESCRIPTIO	N	QTY	UOM	UNIT PRICE	TOTAL
1.1	CCTV SURVEILLANCE SYST	ΓEM UPGRADE	1	LOT	\$	\$
These	ERAL INSTRUCTIONS: specifications have been written to led by the vendor responding to the		equipme	ent and p	performance re	quirements to be
	Government of Guam may conceability and compliance with the pr		-	_		n to determine
suppli	uccessful bidder shall furnish all in led. Installation of IP CCTV Surve on. Successful Bidder shall supply,	illance System will be a	t 542 No	rth Mari	ine Corps Driv	e, Upper Tumon
	accessful bidder shall provide on-si (3) DPW Authorized Personnel.	te training and instruction	on in the	operatio	on of the survei	llance system to
SPEC	CIFICATIONS:			BIDD	ING ON / RE	MARKS:
	Current CCTV Surveillance System CCTV Workstation: Hardware: AMD Athlo 2.907 MHz. 3.25GB of RAM; Operating System Crosoft Windows XP Version 2002 Serv Total Hard Disk Space: 465GB; Used: 327GAlarm System: RISG Products (http://www.kVideo System: Web Servicer (http://video-services.com/doi/10.1006/j.	n TM 64x2 Dual Core, tem: ice Pack 3; B (Free Space 138GB); tershawsystems.com/); erver-e-software.informer.com/)				
	 Bidding on IP CCTV Surveilland or better. Supply, installation, testing and Fast-acting IP CCTV Surveilland Supply, power distribution and Bidder shall include all expensed Of all cameras with power supply Complete with software; Cables shall be outdoor all weat Conduits Video management software shall 	commissioning high quace system along with porequired accessories; incurred in commissionly, accessories and other cables and installed	ality ower oning er device: with	2	nd.	
	 Video management software sind Video stream storage management. Power supply unit as required for UPS Power to support all network (switches, recorders, workstation) 	ent; 30 days recording or the entire system. rked devices				

Bidder must specify make and model for all items offered. Complete technical specifications and technical literature

Proposed CCTV Workstation OS: MS Windows 10 Pro 64 bit

Multiple USB ports for flash drive import and export of recordings

Must be submitted at the time of bid submittal.

Processor: Intel Core i9 10th Generation 1090OT, 10 Cores, 20 threads with up to 4.6GHz, 20M Cache,

32GB RAM; 2TB SD or HD Storage;

Total of Forty-Seven (47) each CCTV Surveillance cameras: Nine-teen (19) each IP Indoors rated domes – oscillating; All cameras shall be true cameras. Night/day, high definition (HD), Infrared/night vision, all weathered cameras, and able to access remotely.
Manufacturer: Model: Year: Place of Origin:
- Twenty-Eight (28) each IP outdoor rated IP PTZ/Camera (bullet) All cameras shall be true cameras. Night/day, high definition (HD), infrared/night vision, all weathered camera, a minimum of 36 x optical + 12 x digital
Manufacturer: Model: Year: Place of Origin:
Must provided detailed report on all units identified To determine operation of each units.
Please see attached Exhibit 1: for the listing of the CCTV Camera & Surveillance Location / Hardware and Exhibit 2: for the map for the installation of units.
Thirteen (13) digital video recorder/wireless WPA2 security or better
 ❖ Triple Operation, Motion Detect Sensor, PTZ Control ❖ NTSC Video Format; Split Screen, Zoom ❖ PIP/Sequence, 110VAC; Motion/Activity Recording ❖ Alarm Input/Output − 8 In/2 Out ❖ Web Interface, IE Browser, Client Software ❖ Hard Drive RT4320CD (320GB HDD) Recording Speed: 120 Frames per second ❖ A minimum of 30 minutes of runtime
Manufacturer: Model: Year: Place of Origin:
Locations for installations of LED Monitors: One (1) 42' wide screen LED monitor: Wall mount; connection cables; power cable; Keyboard; mouse; Ready to be installed in DPW Monitor Room; The system shall include all playback recordings From this monitor system
Manufacturer: Model: Year: Place of Origin:

DEPARTMENT OF PUBLIC WORKS CCTV Camera & Surveillance Location / HARDWARE

"Revised" Exhibit #1

CAMERA	LOCATION	TYPE OF HARDWARE	LOCK BOX - LOC	VIDEO RECORDER LOCATION	
1	Sentry Entrance (Front Entrance)	Bullet	Inside Sentry	1	Inside sentry booth
2	Sentry Entrance (Back Exit)	Bullet	Inside Sentry		Inside sentry booth
3	Warehouse Office (inside-front) (new camera)	Dome - Oscillating	TMC office		TMC Office First FLR
4	Monitor room (backside outside)	Bullet	Tam. Sta Inside	2	Tam. Station Office
5	Monitor room (front side outside)	Bullet	Tam. Sta Inside		Tam. Station Office
6	Monitor room (front of Taunting Bus Station)	Bullet	Tam. Sta Inside		Tam. Station Office
7	Monitor room (rear of Tamuning Bus Station)	Bullet	Tam. Sta Inside		Tam. Station Office
8	Monitor Room inside (back area)	Dome - Oscillating	Tam. Sta Inside	3	Inisde Monitor RM
9	Monitor Room inside (front area)	Dome - Oscillating	Tam. Sta Inside		Inisde Monitor RM
10	Bus Operations (rear backside)	Bullet	Bus Op Ofc	4	Bus Ops Office
11	Federal Highway Bldg. (Front left)	Bullet	TMC office	5	TMC Office First FLR
12	Federal Highway Bldg. (front right)	Bullet	TMC office		TMC Office First FLR
13	Federal Highway Bldg. (Lower front left)	Dome - Oscillating	TMC office		TMC Office First FLR
14	Federal Highway Bldg. (Lower front right)	Dome - Oscillating	TMC office	_	TMC Office First FLR
	Federal Highway Bldg. (Garage-Inside Front) (new				
15	camera)	Dome - Oscillating	TMC office		TMC Office First FLR
16	Highway Encroachment (inside)	Dome - Oscillating	TMC office		TMC Office First FLR
17	Building A (Front of Permit Center)	Bullet	Dir's OFC	6	Director's Office
18	Director's Office (Rear left side)	Dome - Oscillating	Dir's OFC		Director's Office
19	Director's office (Front Entrance)	Bullet	Dir's OFC		Dircector's Office
20	Director's office (Rear left side)	Bullet	Dir's OFC		Director's Office
21	Building Permits (inside)	Dome - Oscillating	Dir's OFC		Director's Office
22	Heavy Equipment shop (rear right outside)	Bullet	Heavy Equip Shop	7	Heavy Equip
23	Heavy Equipment shop (rear left outside)	Bullet	Heavy Equip Shop		Heavy Equip
24	Heavy Equipment shop (rear right inside)	Dome - Oscillating	Heavy Equip Shop		Heavy Equip
25	Heavy Equipment shop (rear left inside)	Dome - Oscillating	Heavy Equip Shop		Heavy Equip
26	Transportation Maintenance (front side GPD)	Bullet	TM Office	8	TM Office 2nd Floor
27	Transportation Maintenance (rear side GPD)	Bullet	TM Office		TM Office 2nd Floor
28	Transportation Maintenance (front side (GPD)	Bullet	TM Office		TM Office 2nd Floor
29	Transportation Maintenance (inside rear)	Dome - Oscillating	TM Office		TM Office 2nd Floor
30	OHS and Admin Office (Back Left)	Bullet	OHS Office	9	OHS Office
.31	OHS and Admin Office (back Right)	Bullet	OHS Office		OHS Office
32	OHS and Admin Office (Front Left)	Bullet	OHS Office		OHS Office
33	OHS and Admin Office (front Right)	Bullet	OHS Office		OHS Office
34	Highway Maintenance (Rear Left Side)	Bullet	HMC Office	10	HMC Shop Office
35	Highway Maintenance (Back Side)	Bullet	HMC Office		HMC Shop Office
36	Highway Maintenance (Rear Right Side)	Dome - Oscillating	HMC Office		HMC Shop Office
37	Laboratory Building (front left)	Bullet	Lab Bldg, inside	11	Inside Lab Building
1.00	Laboratory Building (front right)	Bullet	Lab Bldg, inside		Inside Lab Building
	Laboratory Building (Back left)	Bullet	Lab Bldg, inside		Inside Lab Building
	TM Light Auto shop (rear front side)	Bullet	TM LA Shop	12	LA Shop Office
- 1	TM Light Auto shop (rear back side)	Bullet	TM LA Shop		LA Shop Office
i	TM Light Auto shop (rear inside front)	Dome - Oscillating	TM LA Shop		LA Shop Office
	TM Light Auto shop (rear inside back)	Dome - Oscillating	TM LA Shop		LA Shop Office
	TM Light Auto/Tire Shop (inside back)	Dome - Oscillating	TM LA Shop		LA Shop Office
	TM Light Auto/Tire Shop (inside front)	Dome - Oscillating	TM LA Shop		LA Shop Office
4.7	Ent Signi Autor the Shop (Histae Hollt)	Done - Osemating	BM Office		BM Shop Office
46	Building Maintenance (Right rear side) (new camera)	Dome - Oscillating		13	See Attachment A & B BM Shop Office
47	Building Maintenance (left rear side) (new camera)	Dome - Oscillating	BM Office		See Attachment A & B


Note: 28 Bullet Cameras


15 Dome-Oscillating Cameras


Additional Cameras:

(4) Dome-Oscillating

13 13







Revised 02/10/23 Page 38 of 38